

ਵੱਲ

Principal,
Sohrab Public School,
Nabha Road, Malerkotla.

ਨੰਬਰ 174

ਮਿਤੀ: 08/06/2023

ਵਿਸ਼ਾ:-

ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

SOHRAB PUBLIC SCHOOL, NABHA ROAD, DISTT. MALERKOTLA


ਹਵਾਲਾ:-

ਆਪ ਦਾ ਪੱਤਰ ਨੰਬਰ SPS/MLK/10344 ਮਿਤੀ 10-05-2023

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਸਬੰਧੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਇਸ ਉਪ ਮੰਡਲ ਦੇ ਸਹਾਇਕ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਬਿਲਡਿੰਗ ਦਾ ਨਿਰੀਖਣ ਕਰਨ ਉਪਰੰਤ ਰਿਪੋਰਟ ਕੀਤੀ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਸਾਲ 2023-24 (31.03.2024) ਤੱਕ ਬਾਹਰੇ ਵੇਖਣ ਵਿੱਚ ਸੇਫ ਜਾਪਦੀ ਹੈ। ਇਸ ਤੋਂ ਇਲਾਵਾ ਇਹ ਵੀ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਬਿਲਡਿੰਗ ਵਿਚ ਜੇਕਰ ਕੋਈ ਵੀ ਅਡੀਸ਼ਨਲ ਆਲਟਰੇਸ਼ਨ ਕਰਨੀ ਹੈ ਤਾਂ ਕਿਸੇ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈਕ ਕਰਵਾਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ ਜੇਕਰ ਹੜ੍ਹ, ਕੁਦਰਤੀ ਆਫ਼ਤ ਨਾਲ ਕੋਈ ਵੀ ਦੀਵਾਰ, ਨੀਂਹ ਬਹਿੰਦੀਆਂ ਹਨ ਤਾਂ ਉਸ ਬਾਰੇ ਵੀ ਟੈਕਨੀਕਲ ਕੁਆਲੀਫਾਈਡ ਇੰਜੀਨੀਅਰ ਪਾਸੋਂ ਚੈਕ ਕਰਵਾ ਕੇ ਤਸਦੀਕ ਕਰਵਾਇਆ ਜਾਵੇ। ਇਸ ਦੀ ਇੰਸਪੈਕਸ਼ਨ ਫੀਸ ਇਸ ਦਫ਼ਤਰ ਦੀ ਜੀ.ਆਰ ਨੰ: 665440 ਮਿਤੀ 09-06-2023 ਰਾਹੀਂ 15,000/- ਰੁਪਏ ਜਮਾਂ ਕਰਵਾ ਲਈ ਗਈ ਹੈ।

ਇਸ ਤੋਂ ਇਲਾਵਾ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਸਰਕਾਰ ਦੀਆਂ ਹਦਾਇਤਾਂ ਅਨੁਸਾਰ ਸਕੂਲ ਵੱਲੋਂ ਸੜਕ ਤੋਂ ਅਪਰੇਚ ਲੈਣ ਸਬੰਧੀ ਐੱਨ.ਓ.ਸੀ. ਲਿਆ ਜਾਣਾ ਲੋੜੀਂਦਾ ਹੈ, ਇਸ ਸਬੰਧੀ ਵੱਖਰਾ ਕੇਸ ਮੰਡਲ ਦਫ਼ਤਰ ਪਾਸ ਜਮ੍ਹਾਂ ਕਰਵਾਇਆ ਜਾਵੇ ਜੇਕਰ ਆਪ ਵੱਲੋਂ ਐੱਨ.ਓ.ਸੀ ਨਹੀਂ ਲਿਆ ਜਾਂਦਾ ਤਾਂ ਅਗਲੇ ਸਾਲ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਨਹੀਂ ਕੀਤਾ ਜਾਵੇਗਾ।

ਨੱਥੀ/ਸੇਫਟੀ ਰਿਪੋਰਟ


ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ

ਪਿੱਠ ਅੰਕਣ ਨੰ:

ਮਿਤੀ

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ, ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ, ਭਵਨ ਤੇ ਮਾਰਗ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ ਜੀ ਨੂੰ ਉਨ੍ਹਾਂ ਦੇ ਦਫ਼ਤਰੀ ਪੱਤਰ ਨੰ:1371-73 ਮਿਤੀ 06-06-2023 ਦੇ ਦਿੱਤੇ ਦਿਸ਼ਾ-ਨਿਰਦੇਸ਼ ਅਨੁਸਾਰ ਜਾਰੀ ਕੀਤਾ ਗਿਆ ਹੈ ਅਤੇ ਇਹ ਆਪ ਜੀ ਨੂੰ ਸੂਚਨਾ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ,
ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ:2
ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਮਾਲੇਰਕੋਟਲਾ


Building Safety Report

Name of School: - SOHRAB PUBLIC SCHOOL, NABHA ROAD, DISTT. MALERKOTLA

As per report of Sh. Sudarsh Kumar Assistant Engineer on his visually inspection, the above mentioned school seems visually safe subject to the following observations and conditions:

1. The Parameters to check the stability and safety of building such as Structural Design, Architectural Drawings, Bearing capacity, Foundation details, Structural drawings, Technical Specifications, Test reports of Material used and Quality control reports are not available.
2. In case any addition, alteration, expansion and modification to this building are required/to be done, regarding this, inspection of undersigned may be arranged and obtained a certificate after the completion from the undersigned.
3. In the case of building is affected by flood or if there is any settlement of walls foundation of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.
4. A separate certificate regarding Fire Fighting should be obtained from the competent Authority.
5. A separate certificate regarding Electrical works should be obtained from the competent Authority.
6. The owner of the building/ Management is fully responsible regarding safety of the building from all angles in spite of this report.
7. This report is for the covered area of the school building 65500 Sft which is submitted by the owner of the school building as per drawing.
8. The building of the school is constructed as framed structure/brick masonry.
9. This report is not valid for legal purpose.
10. That the fee charges for the year 2023-2024 is 15,000/-

As per visually inspection as reported by the concerned Assistant Engineer the above building may be used for normal use for One year up to 31-3-2024 subject to the above conditions.


Sub-Divisional Engineer,
Const. Sub-Division No2.
PWD B&R Malerkotla